

Mask Layouts


Single Layer Mask (single field centered within the plate)



Mask Layouts


Single Layer Mask (single field centered within the plate)





Mask plate (5x5)" ~ (127x127)mm2

Quarter with BL orientation writing the <u>program TESTQ</u>



- AUTOSTEP200: LOG IN [10,1]
- CHUCK:142 (for ¼ of 2" pieces or smaller substrates then 2")
- Diameter= 55mm (if 1/4 of 2 inch)
- Cell size (die size):
 X=7.5750mm, Y=8.0000mm
- Gap between die=0.5mm
- Step size (step from die to die):
 X=8.0750mm, Y=8.5000mm
- Distance from DIE center to the lower left corner:

X/2=3.7875mm Y/2=4.0000mm

Adding <u>1 mm from</u> the corner in X, and Y direction bring coordinates for x,y:

X=3.7875+1.0=4.7875mm Y=4.0000+1.0=5.0000mm

This is the pass shift for BL orientation:

PASS SHIFT: x=+4.7875, y=-5.0000

First layer (Layer#1 or your first lithography) Running the job: EX TESTQ, pass: 1

BL: Left objective (R3, C1), Right objective (R3, C3),

Press "A" on the key board, the stage moves, and left objective should be positioned above R3C1


Find the lower left corner of your substrate

Press "D" (to switch movement from die to die)

Aligning takes time (align well along x- axis, and y-axis)!


The left objective should be positioned above R3C1 prior exposing

Key offset is : x=0, y=0; PASS SHIFT: x=+4.7875, y=-5.0000



How to expose first layer (aligning to the LL(lower left)corner of sample)

Orientation A - BL




If 0.5mm is added along the edges (x,y). In my calculation I added 1mm along the edges!

How to align

- Find the proper chuck, load the sample on the chuck, use screws to help in positioning the sample always at the same place (turn ON the vacuum)
- Load chuck on the stage (turn ON the vacuum)
- Press "A" on the keyboard to move the stage, so LEFT objective is above die R3C1
- Find the BL corner
- Press button "D" on the key board, and press on arrow → to step from die to die. Be careful, step as many times as the number of dies you have in that direction (if you have 3 columns, you can step 3X). Be slow and meticulous. Stay on the sample.
- If you step out of sample you might receive the message "Q" for quit. Press "red" button inside of the chamber and start all over with the aligning
- Once aligning is complete (always use right window on monitor for aligning), go back to die R3C1, so LEFT objective is above die R3C1, press expose
- Watch the numbers on voltmeter (column height). This should be in range of -10V to 10V. Ideal focus would be around 0V.

Quarter with BR orientation writing the program TESTQ



- AUTOSTEP200: LOG IN [10,1]
- CHUCK:142 (for ¼ of 2" pieces) or smaller then 2")
- Diameter= 55mm (if 1/4 of 2 inch)
- Cell size (die size):
 X=7.5750mm, Y=8.0000mm
- Gap between die=0.5mm
- Step size (step from die to die): X=8.0750mm, Y=8.5000mm
- Distance from DIE center to the lower left corner:

X/2=3.7875mm Y/2=4.0000mm

Adding <u>1 mm from</u> the corner in X, and Y direction bring coordinates for x,y:

X=3.7875+1.0=4.7875mm Y=4.0000+1.0=5.0000mm

This is the pass shift for BL orientation:

PASS SHIFT: x=-4.7875, y=-5.0000

First layer (Layer#1 or your first lithography)

Running the job: EX TESTQ, pass: 2

BR orientation: L objective (R3,C1), R objective (R3,C3)

Do Not use "A" for this orientation!


Find the lower right corner

Press "D" (to switch movement from die to die)

Aligning takes time (align well along x- axis, and y-axis)!


The right objective should be positioned above R3C3 prior exposing

Key offset is : x=0, y=0; PASS SHIFT: x=-4.7875, y=-5.0000



How to expose first layer (aligning to the LR(lower right)corner of sample))

Orientation B - BR



If 0.5mm is added along the edges (x,y). In my calculation I added 1mm along the edges!

How to align

- Find the proper chuck, load the sample on the chuck, use screws to help in positioning the sample always at the same place (turn ON the vacuum)
- Load chuck on the stage (turn ON the vacuum)
- Find the BR corner
- Press button "D" on the key board, and press on arrow → to step from die to die. Be careful, step as many times as the number of dies you have in that direction. Be slow and meticulous. Stay on the sample.
- If you step out of the sample you might receive the message "Q" and option to quit. Press "red" button inside of the chamber (lower, left side) and you have to start all over with aligning
- Once aligning is complete (always use right window on monitor for aligning), make sure your RIGHT objective is above die R3C3, press expose
- Watch the numbers on voltmeter (column height). This should be in range of -10V to 10V. Ideal focus would be around 0V.