

Linde Gas LLC (216) 642-6600 P.O. Box 94737 Cleveland, Ohio 44101 www.us.lindegas.com MATERIAL SAFETY DATA SHEET

No. 138

PRODUCT NAME Hydrogen lodide	CAS#	10034-85-2	
TRADE NAME AND SYNONYMS	DOT I.D. No.:	Un 2197	
Hydrogel Iodide; anhydrous (D.O.T.) CHEMICAL NAME AND SYNONYMS	DOT Hazard Class:	Division 2.3	
Hydrogen Iodide; Anhydrous Hydriodic Acid	Formula	HI	
ISSUE DATES AND REVISIONS	Chemical Family:	Anhydrous Inorganic Acid	
Revised September 1996		, , , , , , , , , , , , , , , , , , , ,	

HEALTH HAZARD DATA

TIME WEIGHTED AVERAGE EXPOSURE LIMIT

None listed (ACGIH 1994-1995). OSHA 1993, PEL (8 Hr. TWA) = None listed.

SYMPTOMS OF EXPOSURE

Corrosive and irritating to the upper and lower erspiratory tracts, skin and eyes. It hydrolyzes very rapidly yielding hydriodic acid. Skin burns and mucosal irritation are like that from exposure to volatile inorganic acids. Symptoms include lacrymation, cough, labored breathing and excessive salivary and sputum formation. Excessive irritation of the lungs causes acute pneumonitis and pulmonary edema which could be fatal

(Continued on Page 4)

TOXICOLOGICAL PROPERTIES

Hydrogen iodide is irritating and corrosive to all living tissue. Toxic level exposure to dermal tissue causes hydriodic acid burns and skin lesions resulting in early necrosis and scarring. Chemical pneumonitis and pulmonary edema result from exposure to the lower respiratory tract and deep lung. Residual pulmonary malfunction might also occur. Burns to the eye result in lesions and possible loss of vision.

Hydrogen iodide is not I, sted in the IARC, NTP or by OSHA as a carcinogen or potential carcinogen.

(Continued on page 4)

RECOMMENDED FIRST AID TREATMENT

PROMPT MEDICAL ATTENTION IS MANDATORY IN ALL CASES OF OVEREXPOSURE TO HYDROGEN IODIDE. RESCUE PERSONNEL SHOULD BE EQUIPPED WITH SELF-CONTAINED BREATHING APPARATUS.

Inhalation: Conscious persons should be assisted to an uncontaminated area and inhale fresh air. Unconscious persons should he moved to an uncontaminated area and given assisted respiration and supplemental oxygen. Keep the victim warm and quiet. Assure that mucus or vomited material does not obstruct the airway by positional drainage. Delayed pulmonary edema may occur. Keep patient under medical observation for at least 24 hours.

(Continued on Page 4)

Information contained in this material safety data sheet is offered without charge for use by technically qualified personnel at their discretion and risk. All statements, technical information and recommendations contained herein are based on tests and data which we believe to be reliable, but the accuracy or completeness thereof is not guaranteed and no warranty of any kind is made with respect thereto. This information is not intended as a license to operate under or a recommendation to practice or infringe any patent of this Company or others covering any process, composition of matter or use.

Since the Company shall have no control of the use of the product described herein, the Company assumes no liability for loss or damage incurred from the proper or improper use of such product.

HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES

Reacts with the moisture in the atmosphere yielding dense, acrid, hydriodic acid fumes fluorine, calcium carbide, cesium carbide, rubidium carbide and lithium silicide.

. Also reacts hazardously with

(Continued on Page 4)

PHYSICAL DATA			
-32.1°F (-35.6°C)	LIQUID DENSITY AT BOILING POINT 174.4 lb/ft³ (2793 kg/m³)		
WAPOR PRESSURE @ 70°F (21.1°C)= 109.7 psia (756.4 kPa)	GAS DENSITY AT 70°F. 1 atm 337 lb/ft³ (5.400 kg/m³)		
SOLUBILITY N WATER Forms hydriodic acid FREEZING POINT -60.3°F (-51.3°C)			
EVAPORATION RATE N/A (Gas)	© 70°F (21.1°C) = 4.5		
APPEARANCE AND ODOR Colorless gas reacts with moisture in air forming pungent, su ffocating fumes.			

FIRE AND EXPLOSION HAZARDDATA

FLASH POINT (Method used) N/A	AUTO IGNITION TEMPERATURE N/A	FLAMMAB LE N/A	LE LIMITS % BY VOLUME (See Page 4) UEL N/A
EXTINGUISHING MEDIA			ELECTRICAL CLASSIFICATION
Nonflammable gas			Nonhazardous
SPECIAL FIRE FIGHTING PROCEDURES			
If cylinders are exposed to a fire, safely relocate or keep cool with water spra y.			
UNUSUAL FIRE AND EXPLOSION HAZARDS			
None			

REACTIVITY DATA

stability Unstable		CONDITIONS TO AVOID None	
Stable	X		
INCOMPATIBILITY (Materials toavoid) Water, organic materials			
HAZARDOUS DECOMPOSITION PRODUCTS Hydriodic acid on hydrolysis			
HAZARDOUS POLYMERIZATI May Occur	ION	CONDITIONS TO AVOID	
Will Not Occur	Х	None	

SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Evacuate all personnel from a ffected area. Use appropriate protective equipment. If leak is in use r's equipment, be certain to purge piping with an inert gas prior to attempting repairs. If leak is in container or container valve, contact your closest supplier location or call the emergency telephone number listed herein.

WASTE DISPOSAL METHOD

Do not attempt to dispose of waste or unused quantities. Return in the shipping container <u>properly labeled</u>, <u>with any valve outlet plugs or caps secured and valve protection cap in place</u> to your supplie r. For emergency disposal assistance, contact your closest supplier location or call the emergency telephone number listed herein.

SPECIAL PROTECTION INFORMATION

Positive pressure air line with maks or self-contained breathing apparatus should be available for emergency use.			
Hood with forced ventilation		LOCAL EXHAUST To prevent accumulation above the ceiling limit for iodine	SPECIAL N/A
		MECHANICAL (Gen.) N/A	OTHER N/A
PROTECTIVE GLOVES Kel-F® or Teflon®			
EYE PROTECTION Safety goggles or glasses			
отнея ряотестіve equipment Safety shoes, ssfety shower, eyewash "fountain," face shield			

SPECIAL PRECAUTIONS*

SPECIAL LABELING INFORMATION			
DOT Shipping Name:	Hydrogen iodide, anhydrous	DOT Hazard Class:	Division 2.3
DOT Shipping Label:	Toxic Gas	I.D. No.:	UN 2197

SPECIAL HANDLING RECOMMENDATIONS

Use only in well-ventilated areas. Valve protection caps must remain in place unless container is secured with valve outlet piped to use point. Do not drag, slide or roll cylinders. Use a suitable hand truck for cylinder movement. Use a pressure reducing regulator when connecting cylinder to lower pressure (<250 psig) piping or systems. Do not heat cylinder by any means to increase the discharge rate of product from the cylinder. Use a check valve or trap in the discharge line to prevent hazardous backflow into the cylinder.

For additional handling recommendations, consult Compressed Gas Association's Pamphlet P-1.

SPECIAL STORAGE RECOMMENDATIONS

Protect cylinders from physical damage. Store in cool, dry, well-ventilated area away from heavily trafficked areas and emergency exits. Do not allow the temperature where cylinders are stored to exceed 125°F (52°C). Cylinders should be stored upright and firmly secured to prevent falling or being knocked over. Full and empty cylinders should be segregated. Use a "first in - first out" inventory system to prevent full cylinders being stored for excessive periods of time.

For additional storage recommendations, consult Compressed Gas Association's Pamphlet P-1.

SPECIAL PACKAGING RECOMMENDATIONS

Most metals corrode rapidly with wet hydrogen iodide.

OTHER RECOMMENDATIONS OR PRECAUTIONS

Compressed gas cylinders should not be refilled except by qualified producers of compressed gases. Shipment of a compressed gas cylinder which has not been filled by the owner or with his (written) consent is a violation of Federal Law (49CFR).

(Continued on Page 4)

Hydrogen Iodide

HEALTH HAZARD DATA

SYMPTOMS OF EXPOSURE: (Continued)

Hydriodic acid burns exhibit severe pain, redness, possible swelling and early necrosis.

TOXICOLOGICAL PROPERTIES: (Continued)

Persons in ill health where such illness would be aggravated by exposure to hydrogen iodide should not be allowed to work with or handle this product.

RECOMMENDED FIRST AID TREATMENT: (Continued)

Eye Contact: PERSONS WITH POTENTIAL EXPOSURE TO BYDROGEN IDODIDE SHOULD NOT WEAR

CONTACT LENSES.

Flush contaminated eye(s) with copious quantities of water. Part eyelids to assure complete flushing. Continue for a minimum of 15 minutes.

Skin Contact: Flush affected area with copious quantities of water. Remove affected clothing as rapidly as possible.

HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES: (Continued)

Moist hydrogen iodide reacts with most metals in a corrosive manner liberating flammable hydrogen gas. It reacts with many organic materials with the liberation of heat.

SPECIAL PRECAUTIONS

OTHER RECOMMENDATIONS OR PRECAUTIONS: (Continued)

Always secure cylinders in an upright position before transporting them. NEVER transport cylinders in trunks of vehicles, enclosed vans, truck cabs or in passenger compartments. Transport cylinders secured in open flatbed or in open pick-up type vehicles.

Reporting under SARA, Title JII, Section 313 not requireci.

NFPA 704 No. for hydrogen iodide = 3 0 0 Ncne