DOW CORNING CORPORATION Material Safety Data Sheet

Page: 1 of 10 Version: 2.1 Revision Date: 2009/02/23

FOX(R) -16 FLOWABLE OXIDE

1. PRODUCT AND COMPANY IDENTIFICATION

Dow Corning Corporation South Saginaw Road Midland, Michigan 48686
 24 Hour Emergency Telephone:
 (989) 496-5900

 Customer Service:
 (989) 496-6000

 Product Disposal Information:
 (989) 496-6315

 CHEMTREC:
 (800) 424-9300

MSDS No.: 02359791

Revision Date: 2009/02/23

Generic Description: Silicone resin solution. Physical Form: Liquid Color: Colorless Odor: Solvent odor.

NFPA Profile: Health 2 Flammability 3 Instability/Reactivity 1

Note: NFPA = National Fire Protection Association

2. HAZARDS IDENTIFICATION

POTENTIAL HEALTH EFFECTS

Acute Effects

Eye: Direct contact may cause moderate irritation. Vapor may cause eye irritation.

Skin: May cause mild irritation.

Inhalation: Irritates respiratory passages very slightly. Overexposure by inhalation may cause drowsiness, dizziness, confusion or loss of coordination.

Oral: Aspiration of liquid while vomiting may injure lungs seriously.

Prolonged/Repeated Exposure Effects

Skin: Repeated or prolonged contact may cause defatting and drying of skin which may result in skin irritation and dermatitis.

Inhalation: Overexposure by inhalation may injure the following organ(s): Liver. Kidneys. Lungs. Nervous system.

Oral: Repeated ingestion or swallowing large amounts may injure internally.

Signs and Symptoms of Overexposure

No known applicable information.

Medical Conditions Aggravated by Exposure

DOW CORNING CORPORATION Material Safety Data Sheet

Page: 2 of 10 Version: 2.1 Revision Date: 2009/02/23

FOX(R) -16 FLOWABLE OXIDE

No known applicable information.

The above listed potential effects of overexposure are based on actual data, results of studies performed upon similar compositions, component data and/or expert review of the product. Please refer to Section 11 for the detailed toxicology information.

3. COMPOSITION/INFORMATION ON INGREDIENTS

CAS Number	<u>Wt %</u>	Component Name
108-10-1	> 60.0	Methyl isobutyl ketone
137125-44-1	15.0 - 40.0	Hydrogen silsesquioxane
108-88-3	1.0 - 5.0	Toluene

The above components are hazardous as defined in 29 CFR 1910.1200.

4. FIRST AID MEASUR	RES
Eye:	Immediately flush with water for 15 minutes. Get medical attention.
Skin:	Remove from skin and wash thoroughly with soap and water or waterless cleanser. Get medical attention if irritation or other ill effects develop or persist.
Inhalation:	Remove to fresh air. Get medical attention if ill effects persist.
Oral:	Get immediate medical attention. Only induce vomiting at the instructions of a physician. Never give anything by mouth to an unconscious person.
Notes to Physician:	Treat according to person's condition and specifics of exposure.

5. FIRE FIGHTING MEASURES

Flash Point:	60.8 °F / 16 °C (Closed Cup)	
Autoignition Temperature:	Not determined.	
Flammability Limits in Air:	Not determined.	
Extinguishing Media:	On large fires use AFFF alcohol compatible foam or water spray (fog). On small fires use AFFF alcohol compatible foam, CO2 or water spray (fog). Water can be used to cool fire exposed containers. Do not allow extinguishing medium to contact container contents. Most fire extinguishing media will cause hydrogen evolution. When the fire is put out, hydrogen may accumulate in poorly ventilated or confined areas and result in flash fire or explosion if ignited. Foam blankets may also trap hydrogen or flammable vapors, with the possibility of subsurface explosion.	

DOW CORNING CORPORATION Material Safety Data Sheet

Page: 3 of 10 Version: 2.1 Revision Date: 2009/02/23

FOX(R) -16 FLOWABLE OXIDE

Unsuitable Extinguishing Media:	Dry chemical.
Fire Fighting Measures:	Self-contained breathing apparatus and protective clothing should be worn in fighting large fires involving chemicals. Determine the need to evacuate or isolate the area according to your local emergency plan. Use water spray to keep fire exposed containers cool.
Unusual Fire Hazards:	Vapors are heavier than air and may travel to a source of ignition and flash back. Static electricity will accumulate and may ignite vapors. Prevent a possible fire hazard by bonding and grounding or inert gas purge.

6. ACCIDENTAL RELEASE MEASURES

Containment/Clean up: Remove possible ignition sources. Determine whether to evacuate or isolate the area according to your local emergency plan. Observe all personal protection equipment recommendations described in Sections 5 and 8. For large spills, provide diking or other appropriate containment to keep material from spreading. If diked material can be pumped, store recovered material in appropriate container. Materials in contact with water, moisture, acids or bases have the potential to generate hydrogen gas. Recovered material should be stored in a vented container. Clean up remaining materials from spill with suitable absorbant. Clean area as appropriate since spilled materials, even in small quantities, may present a slip hazard. Final cleaning may require use of steam, solvents or detergents. Dispose of saturated absorbant or cleaning materials appropriately, since spontaneous heating may occur. Local, state and federal laws and regulations may apply to releases and disposal of this material, as well as those materials and items employed in the cleanup of releases. You will need to determine which federal, state and local laws and regulations are applicable. Sections 13 and 15 of this MSDS provide information regarding certain federal and state requirements.

Note: See section 8 for Personal Protective Equipment for Spills. Call (989) 496-5900, if additional information is required.

7. HANDLING AND STORAGE

Use with adequate ventilation. Avoid eye exposure. Avoid skin contact. Avoid breathing vapor, mist, dust, or fumes. Keep container closed. Do not take internally.

Static electricity will accumulate and may ignite vapors. Prevent a possible fire hazard by bonding and grounding or inert gas purge. Keep container closed and away from heat, sparks, and flame. Product evolves minute quantities of flammable hydrogen gas which can accumulate. Adequately ventilate to maintain vapors well below flammability limits and exposure guidelines. Do not repackage. Do not store in glass containers which may shatter due to pressure build up. Clogged container vents may increase pressure build up. Keep container closed and store away from water or moisture.

8. EXPOSURE CONTROLS / PERSONAL PROTECTION

DOW CORNING CORPORATION Material Safety Data Sheet

Page: 4 of 10 Version: 2.1 Revision Date: 2009/02/23

FOX(R) -16 FLOWABLE OXIDE

Component Ex	posure Lii	<u>mits</u>	
CAS Number	Compon	ent Name	Exposure Limits
108-10-1	Methyl is	obutyl ketone	OSHA PEL (final rule): TWA 100 ppm and ACGIH TLV: TWA 50 ppm, STEL 75 ppm.
108-88-3	Toluene		OSHA PEL (final rule): 8-Hour TWA 200 ppm, Ceiling 300 ppm, 10 minutes maximum duration 500 ppm. ACGIH TLV: TWA 20 ppm.
Engineering Co	ontrols		
Local Ventilation General Ventilati		Recommended. Recommended.	
Personal Prote	ctive Equi	pment for Routine Handling	
Eyes:		Use chemical worker's goggles.	
Skin:	n: Wash at mealtime and end of shift. Contaminated clothing and shoes should be remo soon as practical and thoroughly cleaned before reuse. Chemical protective gloves a recommended.		
Suitable Gloves:	s: Teflon(R). Butyl Rubber. Nitrile Rubber. Polyvinylalcohol. Silver Shield(R). 4H(R).		
Inhalation:		Use respiratory protection unless adequate local exhaust ventilation is provided or exposure assessment demonstrates that exposures are within recommended exposure guidelines. IH personnel can assist in judging the adequacy of existing engineering controls.	
Suitable Respira	tor:	General and local exhaust ventilation is recommended to maintain vapor exposures below recommended limits. Where concentrations are above recommended limits or are unknown, appropriate respiratory protection should be worn. Follow OSHA respirator regulations (29 CFR 1910.134) and use NIOSH/MSHA approved respirators.	
Personal Protective Equipment for Spills			
Eyes:		Use full face respirator.	
Skin:		Wash at mealtime and end of shift. Contaminated clothing and shoes should be removed as soon as practical and thoroughly cleaned before reuse. Chemical protective gloves are recommended.	

DOW CORNING CORPORATION Material Safety Data Sheet

Page: 5 of 10 Version: 2.1 Revision Date: 2009/02/23

FOX(R) -16 FLOWABLE OXIDE

Inhalation/Suitable Respirator: Respiratory protection recommended. Follow OSHA Respirator Regulations (29 CFR 1910.134) and use NIOSH/MHSA approved respirators. Protection provided by air purifying respirators against exposure to any hazardous chemical is limited. Use a positive pressure air supplied respirator if there is any potential for uncontrolled release, exposure levels are unknown, or any other circumstance where air purifying respirators may not provide adequate protection.

Precautionary Measures: Avoid eye exposure. Avoid skin contact. Avoid breathing vapor, mist, dust, or fumes. Keep container closed. Do not take internally. Use reasonable care.

Note: These precautions are for room temperature handling. Use at elevated temperature or aerosol/spray applications may require added precautions. For further information regarding aerosol inhalation toxicity, please refer to the guidance document regarding the use of silicone-based materials in aerosol applications that has been developed by the silicone industry (www.SEHSC.com) or contact the Dow Corning customer service group.

9. PHYSICAL AND CHEMICAL PROPERTIES

	Colorless Solvent odor. 0.90
Solubility in Water: pH: Volatile Content:	 > 65 °C Not determined. Not determined. Not determined. Not determined. 60.8 °F / 16 °C (Closed Cup) Not determined.

Note: The above information is not intended for use in preparing product specifications. Contact Dow Corning before writing specifications.

10. STABILITY AND R	EACTIVITY
Chemical Stability:	Stable.
Hazardous Polymerization:	Hazardous polymerization will not occur.
Conditions to Avoid:	None.
Materials to Avoid:	Oxidizing material can cause a reaction. Water, alcohols, acidic or basic materials, and many metals or metallic compounds, when in contact with product, liberate flammable hydrogen gas, which can form explosive mixtures in air.

DOW CORNING CORPORATION Material Safety Data Sheet

Page: 6 of 10 Version: 2.1 Revision Date: 2009/02/23

FOX(R) -16 FLOWABLE OXIDE

Hazardous Decomposition Products

Thermal breakdown of this product during fire or very high heat conditions may evolve the following decomposition products: Carbon oxides and traces of incompletely burned carbon compounds. Silicon dioxide. Hydrogen. Formaldehyde.

11. TOXICOLOGICAL INFORMATION

Component Toxicology Information

Toxicology studies with laboratory animals and occupational evaluations with humans have found limited evidence of birth defects, low birth weights and delayed growth in offspring resulting from repeated exposures to toluene during pregnancy.

Special Hazard Information on Components

Reproductive Effects

CAS Number <u>Wt %</u> Component Name

108-88-3 1.0 - 5.0 Toluene

Evidence of reproductive effects in humans.

12. ECOLOGICAL INFORMATION

Environmental Fate and Distribution

Complete information is not yet available.

Environmental Effects

Complete information is not yet available.

Fate and Effects in Waste Water Treatment Plants

Complete information is not yet available.

Ecotoxicity Classification Criteria				
Hazard Parameters (LC50 or EC50)	High	Medium	Low	
Acute Aquatic Toxicity (mg/L)	<=1	>1 and <=100	>100	
Acute Terrestrial Toxicity <=100 >100 and <= 2000 >2000				
This table is a dented from UE wine we add To is also we and Disk Assessment AOTA OTD 4470 w 04 4000				

This table is adapted from "Environmental Toxicology and Risk Assessment", ASTM STP 1179, p.34, 1993.

This table can be used to classify the ecotoxicity of this product when ecotoxicity data is listed above. Please read the other information presented in the section concerning the overall ecological safety of this material.



DOW CORNING CORPORATION Material Safety Data Sheet

Page: 7 of 10 Version: 2.1 Revision Date: 2009/02/23

FOX(R) -16 FLOWABLE OXIDE

13. DISPOSAL CONSIDERATIONS

RCRA Hazard Class (40 CFR 261)

When a decision is made to discard this material, as received, is it classified as a hazardous waste? Yes

Characteristic Waste:

lgnitable: D001 Reactive: D003

State or local laws may impose additional regulatory requirements regarding disposal.Call (989) 496-6315, if additional information is required.

14. TRANSPORT INFORMATION

DOT Road Shipment Info	ormation (49 CFR 172.101)
Proper Shipping Name:	Flammable liquids, n.o.s.
Hazard Technical Name:	Methyl isobutyl ketone / Toluene
Hazard Class:	3
UN/NA Number:	UN 1993
Packing Group:	II
Hazard Label(s):	Flammable Liquid
Ocean Shipment (IMDG)	
Proper Shipping Name:	FLAMMABLE LIQUID, N.O.S.
Hazard Technical Name:	Methyl isobutyl ketone / Toluene
Hazard Class:	3
UN/NA Number:	UN 1993
Packing Group:	II
Hazard Label(s):	flammable liquid
Air Shipment (IATA)	
Proper Shipping Name:	Flammable liquid, n.o.s.

DOW CORNING CORPORATION Material Safety Data Sheet

Page: 8 of 10 Version: 2.1 Revision Date: 2009/02/23

FOX(R) -16 FLOWABLE OXIDE

Hazard Technical Name:	Methyl isobutyl ketone / Toluene
Hazard Class:	3
UN/NA Number:	UN 1993
Packing Group:	II
Hazard Label(s):	Flammable Liquid
Remarks:	VENTED PACKAGES ARE FORBIDDEN FOR AIR TRANSPORT.

Call Dow Corning Transportation, (989) 496-8577, if additional information is required.

15. REGULATORY INFORMATION

Contents of this MSDS comply with the OSHA Hazard Communication Standard 29 CFR 1910.1200.

TSCA Status: All chemical substances in this material are included on or exempted from listing on the TSCA Inventory of Chemical Substances.

EPA SARA Title III Chemical Listings

Section 302 Extremely Hazardous Substances (40 CFR 355): None.

Section 304 CERCLA Hazardous Substances (40 CFR 302):

<u>CAS Number</u>	<u>Wt %</u>	<u>Component Name</u>

- 108-10-1 78.0 Methyl isobutyl ketone
- 108-88-3 1.0 Toluene

Section 311/312 Hazard Class (40 CFR 370):

Acute: Yes Chronic: Yes Fire: Yes Pressure: No Reactive: Yes

Section 313 Toxic Chemicals (40 CFR 372):

CAS Number	<u>Wt %</u>	Component Name
108-10-1	78.0	Methyl isobutyl ketone
108-88-3	1.0	Toluene



DOW CORNING CORPORATION Material Safety Data Sheet

Page: 9 of 10 Version: 2.1 Revision Date: 2009/02/23

FOX(R) -16 FLOWABLE OXIDE

Note: Chemicals are listed under the 313 Toxic Chemicals section only if they meet or exceed a reporting threshold.

Supplemental State Compliance Information

California

Warning: This product contains the following chemical(s) listed by the State of California under the Safe Drinking Water and Toxic Enforcement Act of 1986 (Proposition 65) as being known to cause cancer, birth defects or other reproductive harm.

CAS Number	<u>Wt %</u>	Component Name	
108-88-3	1.0 - 5.0	Toluene	Developmental toxin.
Massachusetts			
CAS Number	<u>Wt %</u>	Component Name	
108-10-1	> 60.0	Methyl isobutyl ketone	
108-88-3	1.0 - 5.0	Toluene	
New Jersey			
CAS Number	<u>Wt %</u>	Component Name	
108-10-1	> 60.0	Methyl isobutyl ketone	
137125-44-1	15.0 - 40.0	Hydrogen silsesquioxane	
108-88-3	1.0 - 5.0	Toluene	
Pennsylvania			
CAS Number	<u>Wt %</u>	Component Name	
108-10-1	> 60.0	Methyl isobutyl ketone	
137125-44-1	15.0 - 40.0	Hydrogen silsesquioxane	
108-88-3	1.0 - 5.0	Toluene	



DOW CORNING CORPORATION Material Safety Data Sheet

Page: 10 of 10 Version: 2.1 Revision Date: 2009/02/23

FOX(R) -16 FLOWABLE OXIDE

16. OTHER INFORMATION

Prepared by: Dow Corning Corporation

These data are offered in good faith as typical values and not as product specifications. No warranty, either expressed or implied, is hereby made. The recommended industrial hygiene and safe handling procedures are believed to be generally applicable. However, each user should review these recommendations in the specific context of the intended use and determine whether they are appropriate.

(R) indicates Registered Trademark